

Exterior Painted Surface Touch-up Instructions

For Windows and Doors with Factory Painted Surfaces

For questions call 1-844-332-8288 Monday – Friday, 8 a.m. to 5 p.m. Eastern Standard Time (EST).

Materials Included:

Quantity	Item
1	Touch-up paint bottle including an applicator brush

Materials Required:

- Mild detergent and water
- Clean rag
- Green 3M Scotch-Brite pad, 00 steel wool or 220 grit sandpaper
- Isopropyl alcohol

Touch-up Paint Tips:

For best results, make sure temperatures are between 60°F and 85°F during applications, with night-time temperatures above 40°F.

Paint curing time ranges from 24–48 hours, depending upon conditions. Avoid applying touch-up paint during periods of high humidity or rain. Additional curing time may be required.

Step 1

Clean the surface.

Clean surface with mild detergent and water to remove any dirt, oil, chalk, or other residue.



Step 2

Dull the surface.

Scuff the surface using the green 3M Scotch-Brite pad, 00 steel wool or 220 grit sandpaper until surface is dull or deglossed.



Step 3

Treat the surface.

Wipe surface to be painted with isopropyl alcohol and allow the surface to dry thoroughly.



Step 4

Mix the paint.

Shake touch-up paint bottle vigorously to make sure the contents are thoroughly combined.



Step 5

Apply the paint.

Apply the touch-up paint using even, steady brush strokes. For repair on a larger area, a foam brush technique may provide the best results.



Step 6

Recoat as needed.

If multiple coats are needed, recoat within 15 minutes or after 48 hours of applying the initial coat.



Advanced Repair Information

Contact Silver Line Service Solutions at 1-800-234-4228 for further information if the area to be painted is too large for touch-up paint. A spray repair may be necessary to achieve the best aesthetic results.